



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com)
Submission Date:	Apr 3, 2020 3:51:36 PM MDT
Server Receive Date:	Apr 3, 2020 3:51:58 PM MDT
Reference Number:	20200403-18138393072
Location:	7566 CO-172, Ignacio, CO 81137, USA Apr 3, 2020 3:47:13 PM MDT [View Map]

Information

Name	kenneth.canterbury@crossfire-llc.com
Date	Apr 3, 2020
Select Run	Miera 1
Well Name	MCCAW, LEROY GAS UNIT B 2
API Number	50670891000
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Other Clean up Operator Debris Clean Up Contaminated Soils Replaced/Repaired Tank Signs

Photo of first corrective action completed



Completed work description Corrective Action 1

Cleaned up contaminated soil and fixed bull plug on load line.

Photo of second corrective action completed



Completed work description of corrective action 2
Photo of third corrective action completed

Cleaned up soil at compressor.



Completed work description of corrective action 3
Photo of fourth corrective action completed

Installed new equipment signs



Completed work description
Completed work description of corrective action 4
Summary of all work completed

Cleaned up trash and back drug reject sand pile.
Cleaned up trash and back drug reject sand pile.
Cleaned up contaminated soil under load line and compressor. Installed new equipment sign on containment ring around BGT. Picked up trash around location. Back drug reject sand pile.