

# *Inspection Photos*

*Loc#335188*

*Operator: Terra*

*Inspection #: 692402043*

*Inspection Date: 3/25/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to Southwest.

March 25, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Langstaff RMV Loc#335188



Photo#2:  
Overview of Interim Reclamation area to South

March 25, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Langstaff RMV Loc#335188





Photo#3:  
 Well API#045-22157.  
 March 25, 2020



Photo#4:  
 Subsidence at Well API#045-22157.





Photo#5:  
Cellar grates (covers) are not complete.

March 25, 2020



Photo#6:  
Cellar grates (covers) are not complete.





Photo#7:  
Areas of sparse vegetation, establishment of weeds and gravelly soils.

March 25, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Langstaff RMV Loc#335188





Photo#8:  
Old growth of Thistle and Cocklebur.



Photo#9:  
Old growth of Thistle and Cocklebur.

March 25, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Langstaff RMV Loc#335188