

Inspection Photos

Location Name: LARAMIE ENERGY LLC Winter Flats Federal /11-43-100 Pad

Location ID: 312737



Network: Apr 6, 2020 at 11:57:26 AM MD
Local: Apr 6, 2020 at 11:57:26 AM MD
+39.2865, -108.504

Photo #0903 from entrance to location



Network: Apr 6, 2020 at 11:59:25 AM MD
Local: Apr 6, 2020 at 11:59:25 AM MD
+39.2847, -108.512

Photo #0904 Chemical tank NFPA label weathered and not legible.

Inspection Photos

Location Name: LARAMIE ENERGY LLC Winter Flats Federal /11-43-100 Pad

Location ID: 312737



Photo #0905 Holes in tank containment liner.