

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402363846

Date Received:

04/07/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10559

Name of Operator: SOUTHLAND ROYALTY COMPANY LLC

Address: 400 WEST 7TH STREET

City: FORT WORTH State: TX Zip: 76102

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Elgin, Jerry

jelgin@mspartners.com

Kittinger, Eric

ekittinger@mspartners.com

Blaylock, Connie

cblaylock@mspartners.com

Gallenbeck, Danny

dnr_cogccengineering@state.co.us

dgallenbeck@ctfieldsvc.com

Pesicka, Conor

conor.pesicka@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 689803874

Inspection Date: 03/24/2020

FIR Submit Date: 03/27/2020

FIR Status: _____

Inspected Operator Information:

Company Name: SOUTHLAND ROYALTY COMPANY LLC

Company Number: 10559

Address: 400 WEST 7TH STREET

City: FORT WORTH State: TX Zip: 76102

LOCATION - Location ID: 313404

Location Name: BIG HOLE GULCH UNIT-611N94W

Number: 8SESW

County: MOFFAT

Qtrqr: SESW Sec: 8 Twp: 11N Range: 94W Meridian: 6

Latitude: 40.921250 Longitude: -107.973594

FACILITY - API Number: 05-081-

-00

Facility ID: 297531

Facility Name: BIGHOLE GULCH FEDERAL

Number: 1

Qtrqr: SESW Sec: 8 Twp: 11N Range: 94W Meridian: 6

Latitude: 40.921250 Longitude: -107.973594

CORRECTIVE ACTIONS:

1 CA# 137502

Corrective Action:

Date: 05/27/2020

Install sign to comply with Rule 210.d.

Response: CA COMPLETED

Date of Completion: 04/06/2020

Operator Comment: Tanks in question were reviewed for CA, but no signs were installed. Tanks are the property of the pipeline company, not Southland Royalty Company.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 137503

Corrective Action: Comply with Rule 603.f .

Date: 04/27/2020

Response: CA COMPLETED

Date of Completion: 04/07/2020

Operator Comment: Southland Royalty requests approval to keep tubing on the site to be used for upcoming P&A of this well.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 137504

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 326 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 04/27/2020

Response: CA COMPLETED

Date of Completion: 04/03/2020

Operator Comment: Southland Royalty submitted a Form 6, NOI to P&A this well, on 4/3/20. The BLM has given their approval to plug and the approved sundry and supporting documentation was uploaded with the Form 6.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Per Inspector photos, tanks needing signs belong to the pipeline company. SRC requests approval to leave tubing on site for P&A. SRC has submitted a Form 6, NOI to P&A, as of 4/3/20.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Connie Blaylock

Signed: _____

Title: Regulatory Analyst

Date: 4/7/2020 10:24:08 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402363889	Form 6-submitted

Total Attach: 1 Files