

Inspection Photos

Loc#335434

Operator: Terra

Inspection #: 692402033

Inspection Date: 3/24/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overviews of Location to Northwest.

March 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Federal RWF Loc#335434



Photo#2:

Fill slope that appears to have been seeded. Note one piece of Debris.

March 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Federal RWF Loc#335434



Photo#3:
Areas of senesced Debris weeds.



Photo#4:
Areas of senesced Debris weeds.



March 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Federal RWF Loc#335434



Photo#5:
Erosion and sediment migration concerns are developing on cut slopes

Photo#6:
Erosion and sediment migration concerns are developing on cut slope.

March 24, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Federal RWF Loc#335434



Photo#7:
BMPs require debris clean out.



Photo#8:
BMPs require debris clean out.

March 24, 2020