

# Inspection Photos

4/06/2020

Operator: LARAMIE ENERGY LLC - 10433

Location ID: 383264

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 383264



**Photo 1:** Photo taken from the northeast end of the Location, facing south. Photos 1-4 provide an overview of the Location from south, southwest, west to northwest. Location has been constructed, drilling activities have not been conducted.

**Photo 2:** See comments under photo 1.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location ID: 383264



**Photo 3:** See comments under photo 1. Photo also shows topsoil stockpile on the north end of the Location; No stormwater or stabilization controls have been installed on the soil stockpiles in accordance with Rule 1002.f



**Photo 4:** See comments under photo 1 and photo 3.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC - 10433  
Location ID: 383264



**Photo 5:** Photo taken from the south end of the Location, facing west. Photo shows straw mulch has been installed to stabilize and protect the fill slopes of the Location.



**Photo 6:** Photo taken from the northwest end of the Location, facing east. Photo shows topsoil stockpile on the north end of the Location; No stormwater or stabilization controls have been installed to protect the soil stockpiles in accordance with Rule 1002.f