

# Inspection Photos

Location Name: Anschutz Equus Farms 3-62-20-21 SWNW

Location ID: 444717



**Photo 1 – Tank Batter**



**Photo 2 – Unmarked Risers south of the Separators**

## Inspection Photos

Location Name: Anschutz Equus Farms 3-62-20-21 SWNW

Location ID: 444717



**Photo 3 – Unmarked Risers south of the Separators**




**Photo 4 – Stained Soil at VRUs**

## Inspection Photos

Location Name: Anschutz Equus Farms 3-62-20-21 SWNW

Location ID: 444717



**Photo 5 – Unmarked Risers on Eastside of Location**