

Inspection Photos
Location Name: Amoco-Federal 21-1
Location ID: 312970



Photo 1. Overview of location taken facing east.



Photo 2. Overview of location taken facing south.



Inspection Photos
Location Name: Amoco-Federal 21-1
Location ID: 312970



Photo 3. Label peeling off on left tank. Pit in tank battery behind left tank.



Photo 4. Pit.



Inspection Photos
Location Name: Amoco-Federal 21-1
Location ID: 312970



Photo 5. Stained soil at pump jack.



Photo 6. Stained soil at pump jack.

