

# Inspection Photos

API: 071-06339

Operator: TIMBER CREEK OPERATING

Inspection Date: 4/6/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06339 | Date: 4/6/2020

## Inspection Photos



**Photo 1.** The well sign is posted at meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06339 | Date: 4/6/2020



## Inspection Photos



**Photo 2.** Facing toward the wellhead.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06339 | Date: 4/6/2020



## Inspection Photos



**Photo 3.** There is stained soils which appear to have been leaked out of pipe riser at SE side of location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06339 | Date: 4/6/2020



## Inspection Photos



**Photo 4.** Facing toward stained soil near the pipe riser. It appears dirt was shoveled over top the stained soil.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06339 | Date: 4/6/2020



## Inspection Photos



**Photo 5.** Facing west along the road toward the location. Arrow points to where spill appears to have flowed down the road side. Circled area is area shown in previous 2 photos.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06339 | Date: 4/6/2020



## Inspection Photos



**Photo 6.** Stained soil is observed down the road side.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06339 | Date: 4/6/2020