

Inspection Photos

Loc#335613

Operator: Terra

Inspection #: 692402064

Inspection Date: 3/27/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to North.

March 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Federal Loc#335613




Photo#2:
View of Interim Reclamation area.

March 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Federal Loc#335613



Photo#3:
Well API# 045-11929 with open cellar.



Photo#4:
Well with open cellar.

March 27, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Fderal Loc#335613