

Inspection Photos
Location Name: Lauridson #31-24
Location ID: 318299



Photo 1 WH



Photo 2 Debris: Dead weeds on location and around unused electric panel

Inspection Photos
Location Name: Lauridson #31-24
Location ID: 318299



Photo 3 unused equipment: Unused electric line with exposed wires not marked not LOTO. As you can see in photo gas powered motor has been installed no electric motor.



Photo 4 Debris: Dead weeds on location.