

Inspection Photos  
Operator: BP America  
API#: 067-06983  
Date: 4/8/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Vegetation is progressing with a mixture of grasses such as western wheatgrass and sand dropseed. Vegetation within the project area is similar to reference vegetation (in background).





Photo 3. View of musk thistles within the project area.





Photo 4. View of the southern project area from the southeastern corner facing westward.