

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2020

Submitted Date:

04/09/2020

Document Number:

701000465**FIELD INSPECTION FORM**Loc ID 304631 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 38 PALMER CREST CTCity: SPRING State: TX Zip: 77381**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|----------------|-----------------------------|---------|
| Jones, Greg | (970) 630-3909 | greg.jones@ownresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 269513 | WELL | PR | 03/04/2005 | GW | 125-08790 | SWOPE 1-29 | PR |

General Comment:Routine Inspection

Location

| | | | |
|--------------------|---------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Trail through grass | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|----------------------------|-------|--|
| Signs/Marker: | | | |
| Type | OTHER | | |
| Comment: | Lease signs by meter sheds | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Lease sign by unit | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Metal sign by water tank | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|---|-------|--|
| Fencing/: | | | |
| Type | OTHER | | |
| Comment: | Metal panels around VGS and meter sheds | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | Metal panels around water tank | | |
| Corrective Action: | | Date: | |
| Type | PUMP JACK | | |
| Comment: | Metal panels around unit and wellhead | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|----------------|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Electric panel | | |
| Corrective Action: | | Date: | |

| | | |
|--------------------------|--|-------|
| Type: Gas Meter Run | # 3 | |
| Comment: | Shared meter run for (Swope 1-29, 2-29, 3-29) 600' north of wellhead | |
| Corrective Action: | | Date: |
| Type: Prime Mover | # 1 | |
| Comment: | Electric motor | |
| Corrective Action: | | Date: |
| Type: Vertical Separator | # 3 | |
| Comment: | 3-Vertical gas separators 50% buried by meter sheds | |
| Corrective Action: | | Date: |
| Type: Pump Jack | # 1 | |
| Comment: | Jensen unit | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|----------------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | 200 BBLs | PBV FIBERGLASS | | 39.947060,-102.548550 |
| Comment: | Fiberglass water tank 50% buried on south side of meter sheds | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 269513 | Type: | WELL | API Number: | 125-08790 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. Casing production. Central meter run for (Swope 1-29, 2-29, 3-29) 600' N of wellhead on south side of CR 26 | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

| | | | | | | | | | |
|--|--|--|--|--|--|--|--|--|--|
| | | | | | | | | | |
|--|--|--|--|--|--|--|--|--|--|

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Compaction | Pass | Compaction | Pass | | | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT