

Inspection Photos

Loc#457469

Operator: Terra

Inspection #: 692402074

Inspection Date: 4/3/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overviews of Location to North & South.

April 3, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Federal PA Loc#457469



Photo#2:
Debris/Waste material behind equipment.

April 3, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Federal PA Loc#457469




Photo#3:
Cellar line up; metal cover plate on one conductor pried up/open.

April 3, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#4:
Gaps in cellar grates.

Inspection Photos: Terra Federal PA Loc#457469



Photo#5:
Slough on Cut slope.



Photo#6:
Erosion on Cut slope.

April 3, 2020



Photo#7:
BMP at base of Cut.



Photo#8:
BMP at NE corner.

April 3, 2020



Photo#9:
BMP at first drop to base of Fill.



Photo#10:
BMP at road culvert.

April 3, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Federal PA Loc#457469