

Inspection Photos
Location Name: Northup 1-14
Location ID: 327106



Photo 1 – Tank Battery, Weeds surrounding the Location



Photo 2 – Wellhead. Weeds

Inspection Photos
Location Name: Northup 1-14
Location ID: 327106



Photo 3 – Weeds surrounding the Separator



Photo 4 – Weeds surrounding the Separator

Inspection Photos
Location Name: Northup 1-14
Location ID: 327106



Photo 5 – Wildlife Screen missing from Separator



Photo 6 – Weeds surrounding the Crude Oil Tank

Inspection Photos
Location Name: Northup 1-14
Location ID: 327106



Photo 7 – Weeds surrounding the Produced Water Pit



Photo 8 – Unused Volume Pot, west of Wellhead