

Final Reclamation and Stormwater Inspection

April 8, 2020

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 320328

Inspection Document #: 697501322

Adams County, CO

NESE Section 4 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: EHLER #2-4
Location ID: 320328



Photo 1. Photo taken from the well and battery location, facing South. Photo illustrates Operator has performed final reclamation activities with the evidence of drill rows, straw crimped mulch, and germination.

Inspection Photos
Location Name: EHLER #2-4
Location ID: 320328



Photo 2. Photo taken from the well and battery location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: EHLER #2-4
Location ID: 320328



Photo 3. Photo taken from the well and battery location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: EHLER #2-4
Location ID: 320328



Photo 4. Photo taken from the well and battery location. Photo illustrates Canada thistle rosettes. Operator shall continue to monitor and control all weed species.