

Inspection Photos

Loc#334536

Operator: Laramie

Inspection #: 692402083

Inspection Date: 4/13/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southeast.

April 13, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Hells Gulch Fed Loc#334536



Photo#3:.

Photo#2:

Localized area of stained gravel at middle tank in South tank battery containment.

April 13, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Hells Gulch Fed Loc#334536



Photo#4:
BMP on Pad edge.



Photo#5:
Fill slope.

April 13, 2020