

Inspection Photos  
Location Name: Windsor LV2 14-M Pad  
Location ID: 449441



Photo 1: Wellhead Sign



Photo 2: Wellhead

Inspection Photos  
Location Name: Windsor LV2 14-M Pad  
Location ID: 449441




Photo 3: Stained soil



Photo 4: Wellhead Sign






**Inspection Photos**  
**Location Name: Windsor LV2 14-M Pad**  
**Location ID: 449441**



**Photo 5: Wellhead**



**Photo 6: Stained soil**

Inspection Photos  
Location Name: Windsor LV2 14-M Pad  
Location ID: 449441



Colorado Oil and Gas Conservation Commission  
40.48184, -104.85219, 1450.9m, 90°  
Apr 14, 2020 15:29:38

Photo 7: Tank Battery Sign



Colorado Oil and Gas Conservation Commission  
40.48195, -104.85217, 1453.3m, 117°  
Apr 14, 2020 15:29:50

Photo 8: Tank Battery





**Inspection Photos**  
**Location Name: Windsor LV2 14-M Pad**  
**Location ID: 449441**



**Photo 9: Unused equipment (east) at wellheads**



**Photo 10: Unused equipment**





**Inspection Photos**  
**Location Name: Windsor LV2 14-M Pad**  
**Location ID: 449441**



**Photo 11: Unused riser**



**Photo 12: Debris (south) at separators**





**Inspection Photos**  
**Location Name: Windsor LV2 14-M Pad**  
**Location ID: 449441**



**Photo 13: Debris (NE) at separators**



**Photo 14: Container not in containment**

