

Inspection Photos  
Location Name: Leonard 43-21  
Location ID: 330866



Photo 1 WH sign



Photo 2 WH

# Inspection Photos Location Name: Leonard 43-21 Location ID: 330866



Photo 3 Gas meter run




Photo 4 Card inside meter house

**Inspection Photos**  
**Location Name: Leonard 43-21**  
**Location ID: 330866**



**Photo 5 Horizontal Heated separator area and gas meter run door missing.**



**Photo 6 Meter house door lying behind meter house**



Inspection Photos  
Location Name: Leonard 43-21  
Location ID: 330866



Photo 7 TB signs



Photo 8 TB