

Inspection Photos
Location Name: Cleveland 3
Location ID: 318056



Photo 1 WH sign



Photo 2 WH disassembled PJ equip.

Inspection Photos
Location Name: Cleveland 3
Location ID: 318056



Photo 3 unused transformer and meter box



Photo 4 unused PJ equipment fencing and electric panel.