

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/15/2020

Submitted Date:

04/15/2020

Document Number:

689704574

**FIELD INSPECTION FORM**

Loc ID 440705	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: 10447 Name of Operator: URSA OPERATING COMPANY LLC Address: 950 17TH STREET, SUITE 1900 City: DENVER State: CO Zip: 80202				<b>Findings:</b> 19 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415550	WELL	PR	07/24/2015	GW	045-19092	WATSON RANCH B 23A-17-07-95	PR
415572	WELL	PR	09/15/2015	GW	045-19100	WATSON RANCH B 23C-17-07-95	PR
418498	WELL	PR	09/21/2015	GW	045-19719	WATSON RANCH B 24C-17-07-95	PR
418500	WELL	PR	09/09/2015	GW	045-19721	WATSON RANCH B 24A-17-07-95	PR
440702	WELL	PR	06/01/2015	GW	045-22799	WATSON RANCH B 32C-17-07-95	PR
440703	WELL	PR	08/22/2015	GW	045-22800	WATSON RANCH B 33A-17-07-95	PR
440706	WELL	PR	06/01/2015	GW	045-22802	WATSON RANCH B 33C-17-07-95	PR
440707	WELL	PR	07/08/2015	GW	045-22803	WATSON RANCH B 32B-17-07-95	PR
440708	WELL	PR	07/15/2015	GW	045-22804	WATSON RANCH B 32D-17-07-95	PR
440709	WELL	PR	06/01/2015	GW	045-22805	WATSON RANCH B 34C-17-07-95	PR
440710	WELL	PR	06/01/2015	GW	045-22806	WATSON RANCH B 33D-17-07-95	PR
440711	WELL	PR	06/01/2015	GW	045-22807	WATSON RANCH B 34A-17-07-95	PR
440712	WELL	PR	07/23/2015	GW	045-22808	WATSON RANCH B 33B-17-07-95	PR

<b>General Comment:</b>
-------------------------

This is a summary of inspection report.

On Wednesday 04/15/2020 at approximately 1145 hours, I, Inspector Mike Longworth, conducted a field inspection at URSA OPERATING COMPANY LLC, Watson Ranch B Pad , at Location #440705 in Garfield County, Colorado

During this inspection the following possible compliance issues were observed:

Unmarked deadmen around wells.

Mark guy line anchors per Rule 1003.a.

C.A. Date 05/01/2020

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 5		
Comment:	Unmarked deadmen around wells.		

Corrective Action:	Mark guy line anchors per Rule 1003.a.		Date:	05/01/2020
Type: Bird Protectors	# 7			
Comment:				
Corrective Action:			Date:	
Type: Plunger Lift	# 13			
Comment:				
Corrective Action:			Date:	
Type: Emission Control Device	# 2			
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 13			
Comment:				
Corrective Action:			Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	<50 BBLS	STEEL AST		,	
Comment:	Fuel for injection well operation.					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)	Diesel	
Other (Capacity)	1000 gallons	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal				
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	6	300 BBLs	STEEL AST		,
Comment:	Injection well tank battery				
Corrective Action:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	415550	Type:	WELL	API Number:	045-19092	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	415572	Type:	WELL	API Number:	045-19100	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	418498	Type:	WELL	API Number:	045-19719	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	418500	Type:	WELL	API Number:	045-19721	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	440702	Type:	WELL	API Number:	045-22799	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	440703	Type:	WELL	API Number:	045-22800	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	440706	Type:	WELL	API Number:	045-22802	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	440707	Type:	WELL	API Number:	045-22803	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	440708	Type:	WELL	API Number:	045-22804	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	440709	Type:	WELL	API Number:	045-22805	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	440710	Type:	WELL	API Number:	045-22806	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	440711	Type:	WELL	API Number:	045-22807	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	440712	Type:	WELL	API Number:	045-22808	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass					
		Gravel	Pass			
Ditches	Pass					
		Compaction	Pass			
Berms	Pass					
				Material Handling And Spill Prevention	Pass	
		Ditches	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689704575	Inspection 689704574 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5125130">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5125130</a>