

Inspection Photos
Location Name: Evans 0780 21
Location ID: 438250



Photo 1. Overview of location taken facing southwest.

Inspection Photos
Location Name: Evans 0780 21
Location ID: 438250



Photo 2. Gravel on northern perimeter berm.



Photo 3. Gravel on northern perimeter berm.