

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /24SWNE

Location ID: 312609



Photo #0972 from entrance to location




Photo #0973 Tank capacity and contents not legible.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /24SWNE

Location ID: 312609



Photo #0974 Multiple places with debris on location.



Photo #0975 Multiple places with debris on location.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /24SWNE

Location ID: 312609




Photo #0977 Unused equipment on location.