

Interim Reclamation and Stormwater Inspection

April 15, 2020

Operator: PHOENIX RESOURCES LLC - #10691

Location ID: 420020

Inspection Document #: 697501356

Weld County, CO

NWNW Section 25 T8N R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Cass Farms #11-25H
Location ID: 420020



Photo 1. COGCC GISOnline aerial imagery from 2017 illustrates the total disturbance area. Operator recently performed weed management but did not perform work throughout the entire disturbance area.



Photo 2. Photo taken north of the eastern interim reclamation area, facing South. Photo illustrates Operator did not perform weed management throughout the entire disturbance area.

Inspection Photos
Location Name: Cass Farms #11-25H
Location ID: 420020



Photo 3. Photo taken from the entrance of location, facing East. See comments under Photo 2.



Photo 4. Photo taken from the eastern interim reclamation area, facing Northeast. Photo illustrates the Operator only performed weed management on an approximate ~20-25' width. There is still another 35-40' of interim area that needs to be managed for weeds.



Photo 5. Photo taken from the western interim reclamation area, facing West. See comments under Photo 4.