

# *Inspection Photos*

*Loc#334517*

*Operator: Laramie*

*Inspection #: 692402096*

*Inspection Date: 4/13/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from entry to East.

April 13, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Hells Gulch Fed Loc#334517



Photo#2:  
Overview of Location to Southwest.

April 13, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Hells Gulch Fed Loc#334517



Photo#3:  
Cuttings pile stored at SE Corner.

April 13, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Hells Gulch Fed Loc#334517



Photo#4:  
Erosion on Cut slope.



Photo#5:  
Erosion on Cut slope.

April 13, 2020



Photo#6:  
Ponding of stormwater.



Photo#7:  
Ponding of stormwater.

April 13, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Hells Gulch Fed Loc#334517



Photo#8:  
Ponding and degradation of pad surface.

Photo#9:  
Ponding and degradation of pad surface

April 13, 2020



Photo#10:  
Blocked drains on Pad Fill slope edge.



Photo#11:  
Blocked drains on Pad Fill slope edge.

April 13, 2020



Photo#12:  
View along West Fill slope.



Photo#13:  
Flexible drains running to base of Fill slope.

April 13, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Hells Gulch Fed Loc#334517