

Inspection Photos
Location Name: KRAFT 23-1 R
API#: 05-071-08560
INSP. #: 695102719



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN/ WELL NUMBERS ON BOTH WELL SIGN
ARE NOT LEGIBLE. **COMPLY WITH RULE 210.b. CA DATE 7-20-20.**

Inspection Photos
Location Name: KRAFT 23-1 R
API#: 05-071-08560
INSP. #: 695102719





PHOTO 3: KRAFT 23-1 R GAS METER CAL. REPORT.

PHOTO 4: KRAFT 23-1 V GAS METER CAL. REPORT

Inspection Photos
Location Name: KRAFT 23-1 R
API#: 05-071-08560
INSP. #: 695102719



**PHOTO 5: UNUSED RISER NEAR V WELL. COMPLY WITH RULE
603.f. CA DATE 5-20-20.**