

Inspection Photos
Location Name: HUNTER 22-17
API#: 05-071-09885
INSP. #: 695102722



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos
 Location Name: HUNTER 22-17
 API#: 05-071-09885
 INSP. #: 695102722

Calibration Report

Report Date: 10/21/19 10:00 AM
 Device ID: 105100000
 Location: HUNTER 22-17

System: Contract # 714-400-1000
 Field: Sejan Basin
 State: Colorado
 Producer: Evergreen Natural Resources
 Purchaser: Colorado Interstate Gas

Correct Plate Size: 8.75
 Pipe Size: 3.00
 Approx. Pressure: 11.7
 Pressure - Base: 14.75

Tap Type: Up Stream
 DP Tap Location: 4
 Temperature Unit: °F

Plate Inspected? Yes ☒ No ☐
 Edges Sharp? Yes ☒ No ☐
 Seal Ring Damaged? Yes ☐ No ☒
 Tube Inspected? Yes ☒ No ☐
 Dirty? Yes ☐ No ☒
 Pinned? Yes ☐ No ☒

Specific Gravity: 0.60

Pressure (PSI)	Flow (SCFH)	Flow (GPM)	Flow (MGD)	Flow (MMSCFD)	Flow (MMBtu/hr)	Flow (MMBtu/day)	Flow (MMBtu/year)
10.00	10.00	10.00	10.00	10.00	10.00	10.00	10.00
11.00	11.00	11.00	11.00	11.00	11.00	11.00	11.00
12.00	12.00	12.00	12.00	12.00	12.00	12.00	12.00
13.00	13.00	13.00	13.00	13.00	13.00	13.00	13.00
14.00	14.00	14.00	14.00	14.00	14.00	14.00	14.00
15.00	15.00	15.00	15.00	15.00	15.00	15.00	15.00
16.00	16.00	16.00	16.00	16.00	16.00	16.00	16.00
17.00	17.00	17.00	17.00	17.00	17.00	17.00	17.00
18.00	18.00	18.00	18.00	18.00	18.00	18.00	18.00
19.00	19.00	19.00	19.00	19.00	19.00	19.00	19.00
20.00	20.00	20.00	20.00	20.00	20.00	20.00	20.00

DP Check with pressure on DP: FOUND 11.75
 Cal. Temp: 61.0
 Gas Sample Taken: Yes ☒ No ☐
 H2S Analyzed: Yes ☒ No ☐
 PPM of H2S: 111
 H2O Analyzed: Yes ☒ No ☐

REMARKS: 37.47359, -104.91335, 2340.0m, 61°
 2020/04/20 14:01:28

PHOTO 3: GAS METER CAL. REPORT