

Inspection Photos
Operator: Kinder Morgan
API#: 033-06134
Date: 4/14/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing with young grasses such as western wheatgrass.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photos 4/5. View of musk and Scotch thistles within the project area. Approximately 100 individuals observed.



Photo 6. View of reference area, comprised of gambel oak and black sage shrubland with scattered ponderosa pine trees and grasses such as western wheatgrass and squirreltail in the understory.