

Inspection Photos

Location Name: GOLDEN EAGLE 20-7

API#: 05-071-08052

INSP. #: 695102727



Colorado Oil & Gas Conservation Commission  
37.1616, -104.90645, 2285.0m, 132°  
2020/04/21 12:19:46



  
WDID 1912374  
PERMIT 71288  
**719-497-0446**  
or 911  
GOLDEN EAGLE 20-07  
**SW/NE** 20-33S-67W  
NAD 83  
Lat. 37.161305  
Long. 104.906271

Colorado Oil & Gas Conservation Commission  
37.16138, -104.90613, 2289.0m, 143°  
2020/04/21 12:23:12

PHOTO 1: LOCATION

PHOTO 2: WELL SIGN

Inspection Photos  
Location Name: GOLDEN EAGLE 20-7  
API#: 05-071-08052  
INSP. #: 695102727




PHOTO 3: GAS METER CAL. LOG

PHOTO 4: STANDING OIL IN ENGINE SKID (APPEARS THAT ENGINE OIL IS BEING DRAINED INTO ENGINE SKID). **Comply with general provisions of the oil and gas act for wildlife protection. CA DATE 5-21-20.**

## Inspection Photos

Location Name: GOLDEN EAGLE 20-7

API#: 05-071-08052

INSP. #: 695102727



**PHOTO 5: AREA OF IMPACTED SOIL NEAR ENGINE SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-26-20.**

**PHOTO 6: AREA OF IMPACTED SOIL NEAR ENGINE SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. CA DATE 4-26-20.**

## Inspection Photos

Location Name: GOLDEN EAGLE 20-7

API#: 05-071-08052

INSP. #: 695102727



**PHOTO 7: UNUSED EQUIPMENT STORED ON LOCATION. COMPLY WITH RULE 603.f. CA DATE 5-6-20**

**PHOTO 8: UNUSED EQUIPMENT STORED ON LOCATION. COMPLY WITH RULE 603.f. CA DATE 5-6-20**

Inspection Photos

Location Name: GOLDEN EAGLE 20-7

API#: 05-071-08052

INSP. #: 695102727



**PHOTO 9: APPEARS TO BE TWO PILES OF FRAC SAND ON LOCATION. Immediately comply with material handling and guidance per MSDS or product data sheet. Submit document, procedures, and waste disposal manifest to COGCC field inspector. CA DATE 5-1-20**

**PHOTO 10: GUY LINE ACHOR MARKER IS DOWN. Install proper guy line markers per Rule 1003.a CA DATE 5-5-20**