

Inspection Photos

Location Name: GOLDEN EAGLE 20-02

API#: 05-071-08733

INSP. #: 695102729



Colorado Oil & Gas Conservation Commission
37.16466, -104.90769, 2312.0m, 154°
2020/04/21 13:07:48

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission
37.16437, -104.9074, 2339.0m, 219°
2020/04/21 13:09:53

PHOTO 2: WELL SIGN



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: GOLDEN EAGLE 20-02
API#: 05-071-08733
INSP. #: 695102729




PHOTO 3: GAS METER CAL. LOG.



PHOTO 4: STANDING OILY WATER IN ENGINE SKID.
Comply with general provisions of the oil and gas
act for wildlife protection. CA DATE 5-21-20.

Inspection Photos

Location Name: GOLDEN EAGLE 20-02

API#: 05-071-08733

INSP. #: 695102729



**PHOTO 3: AREA OF IMPACTIED SOIL AROUND
ENGINE SKID. Conduct maintenance on equipment,
cleanup stained material and review self inspection
processes. CA DATE 5-21-20.**

