

Reclamation and Stormwater Inspection

April 22, 2020

Operator: PETROSHARE CORPORATION- 10454

Location ID: 333075

Inspection Document #: 697501386

Adams County, CO

NENW Section 2 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources



Photo 1. Google Earth aerial imagery taken 9/12/2019 illustrating the approximate damage due to vehicle rutting. The approximate area illustrated in red was mapped on 4/8/2020 using a Trimble Juno 3B handheld device.

Inspection Photos
Location Name: GUTHRIE #21-2
Location ID: 333075



Photo 2. Photo taken from the entrance of location on April 8, 2020, facing South along Lansing Ct. Photo illustrates sediment discharge from vehicle tracking on Lansing Ct.



Photo 3. Photo taken from the entrance of location on April 22, 2020, facing South along Lansing Ct. Photo illustrates Operator did minimal to no clean up from vehicle tracking on Lansing Ct.

Inspection Photos
Location Name: GUTHRIE #21-2
Location ID: 333075



Photo 4. Photo taken from the entrance of location on April 8, 2020, facing North. Photo illustrates a damaged culvert from vehicle traffic.



Photo 5. Photo taken from the entrance of location on April 22, 2020, facing North. Photo illustrates Operator repaired damage to the culvert.

Inspection Photos
Location Name: GUTHRIE #21-2
Location ID: 333075



Photo 6. Photo taken from the entrance of location on April 22, 2020, facing Southwest. Photo illustrates Operator has repaired rutting throughout the previously disturbed areas.

Inspection Photos
Location Name: GUTHRIE #21-2
Location ID: 333075



Photo 7. Photo taken from the wellhead on April 22, 2020, facing Southwest.
See comments under Photo 6.

Inspection Photos
Location Name: GUTHRIE #21-2
Location ID: 333075



Photo 8. Photo taken from the wellhead on April 22, 2020, facing Northwest.
see comments under Photo 6.

Inspection Photos
Location Name: GUTHRIE #21-2
Location ID: 333075



Photo 9. Photo taken from northwest of the wellhead on April 22, 2020, facing Northwest. See comments under Photo 6.

Inspection Photos
Location Name: GUTHRIE #21-2
Location ID: 333075



Photo 10. Photo taken west of the wellhead on April 22, 2020, facing South.
See comments under Photo 6.