

Inspection Photos
Location Name: Mark PC GK 11-02 Tank
Location ID: 417831



Photo 1 – Tank Battery





Photo 2 – Unused Secondary Containment

Inspection Photos
Location Name: Mark PC GK 11-02 Tank
Location ID: 417831



Colorado Oil and Gas Conservation Commission
40.93682, -104.16314, 5215.2ft, 235°
04/20/2020 14:12:18

Photo 3 – Produced Water Vault missing Capacity Label



Colorado Oil and Gas Conservation Commission
40.93703, -104.16337, 5219.1ft, 264°
04/20/2020 14:13:13

Photo 4 – Unmarked Riser at Gas Meter