

**Inspection Photos**  
**Location Name: Winter 29-D Pad**  
**Location ID: 433397**




**Photo 1: Wellhead Sign**



**Photo 2: Pumpjack**



**Inspection Photos**  
**Location Name: Winter 29-D Pad**  
**Location ID: 433397**



**Photo 3: Stained Soil**



**Photo 4: Unused equipment**



**Inspection Photos**  
**Location Name: Winter 29-D Pad**  
**Location ID: 433397**



**Photo 5: Unused equipment**



**Photo 6: Wellhead Sign**

**Inspection Photos**  
**Location Name: Winter 29-D Pad**  
**Location ID: 433397**



**Photo 7: Pumpjack**



**Photo 8: Stained soil**





**Inspection Photos**  
**Location Name: Winter 29-D Pad**  
**Location ID: 433397**



**Photo 9: Unused equipment**




**Photo 10: Wellhead Sign**

**Inspection Photos**  
**Location Name: Winter 29-D Pad**  
**Location ID: 433397**



**Photo 11: Pumpjack**



**Photo 12: Stained soil**





**Inspection Photos**  
**Location Name: Winter 29-D Pad**  
**Location ID: 433397**



**Photo 13: Unused equipment**



**Photo 14: Unused equipment**



Inspection Photos  
Location Name: Winter 29-D Pad  
Location ID: 433397




Photo 15: Wellhead Sign



Photo 16: Pumpjack



**Inspection Photos**  
**Location Name: Winter 29-D Pad**  
**Location ID: 433397**



**Photo 17: Unused equipment**



**Photo 18: Trash removed/barrel in containment**

