

Inspection Photos

API: 055-06144

Operator: TABULA RASA ENERGY

Inspection Date: 4/22/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06144 | Date: 4/22/2020

Inspection Photos



Photo 1. Facing west along the access road which is maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06144 | Date: 4/22/2020

Inspection Photos



Photo 2. Facing west toward the location. There are three dumpsters stored at the northwest side of the location. This is a possible safety concern since it is near the well and should be moved off location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06144 | Date: 4/22/2020

Inspection Photos



Photo 3. Facing north toward the well site. The three dumpsters are seen in background within close proximity to the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06144 | Date: 4/22/2020

Inspection Photos



Photo 4. Well sign is posted at the well head. Emergency contact number on the sign needs to be updated.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06144 | Date: 4/22/2020

Inspection Photos



Photo 5. Facing south at the west side of the location. There are numerous t-post in this area. The t-post appear to have no use and should be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06144 | Date: 4/22/2020

Inspection Photos



Photo 6. There is pile of soil material being stored and removed at the east side of the location. This should be leveled and reseeding. This issue is disturbing the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06144 | Date: 4/22/2020

Inspection Photos



Photo 7. Facing back toward the southwest along the fill slope. Soil material has been dumped in this area. This issue is disturbing the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06144 | Date: 4/22/2020