

Inspection Photos
Location Name: Crow Valley 7-62-22-2H
Location ID: 428324



Photo 1 – Tank Battery



Photo 2 – Unused Rods at Pumping Unit

Inspection Photos
Location Name: Crow Valley 7-62-22-2H
Location ID: 428324



Colorado Oil and Gas Conservation Commission
40.55346, -104.31098, 4852.9ft, 272°
04/21/2020 11:32:14

Photo 3 – Unmarked Risers at VRU