

Inspection Photos
Operator: Red Mesa
API#: 067-09337
Date: 4/23/2020



Photo 1. View of the project area from the southwestern corner facing center. Area was mowed in 2019. Facilities not on location. Review of well file documentation indicates that well status is unclear.



Photo 2. View of the southern project area from the southwestern corner facing westward.



Photo 3. View of the westrn project area facing northward from the southern edge.



Photo 4. View of dense kochia seedlings in an early growing condition at this time.



Photo 5. View of reference area vegetation comprised of open sagebrush shrubland with scattered juniper trees Grasses/herbs in the understory such as blue grama, sand dropseed and Indian ricegrass, penstemon spp. are observable in a dormant vegetative condition.