

## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /8SENW

Location ID: 334106



Network: Apr 24, 2020 at 12:52:21 PM MDT  
Local: Apr 24, 2020 at 12:52:21 PM MDT  
+39.3661, -108.135



Network: Apr 24, 2020 at 12:53:34 PM MDT  
Local: Apr 24, 2020 at 12:53:34 PM MDT  
+39.3665, -108.134


Photo #1043 from entrance to location

Photo # 1044 Unused equipment in tank containment

## Inspection Photos

**Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /8SENW**

**Location ID: 334106**



**Photo #0895 from inspection #699800836 conducted on 4/1/20.**