

Inspection Photos
Location Name: Frank Stermole #1
Location ID: 318420



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Frank Stermole #1
Location ID: 318420



Photo 3 pump jack

Photo 4 gas meter run

Inspection Photos
Location Name: Frank Stermole #1
Location ID: 318420



Photo 5 TB sign

Photo 6 Dead weeds inside of TB berm

Inspection Photos
Location Name: Frank Stermole #1
Location ID: 318420



Photo 7 Berm around PW is flat

Photo 8 ECD

Inspection Photos
Location Name: Frank Stermole #1
Location ID: 318420



Photo 9 Horizontal Heated Separator