

Inspection Photos
Location Name: Inexco-State 1
Location ID: 312899



Photo 1. Overview of location taken facing west. Dried annual weeds on location.



Photo 2. Stained soil at wellhead. Dried annual weeds at wellhead.



Inspection Photos
Location Name: Inexco-State 1
Location ID: 312899



Photo 3. Tubing and dried annual weeds.



Photo 4. Apparent sediment migration down access road.