

Inspection Photos

Location Name: EHRlich A-66N64W /34NENE

Location #: 310442



Photo #1

Ehrlich A 34-1 (05-123-26413) Wellsite

Shut-In | SI



Photo #2

Ehrlich A 34-1 Battery site

Inactive | Shut-down



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources