

Inspection Photos
Location Name: Bronco State AF10-64-1HN
Location ID: 431377



Photo 1 – Wellhead



Photo 2 – Tank Battery

Inspection Photos
Location Name: Bronco State AF10-64-1HN
Location ID: 431377



Photo 3 – Signage



Photo 4 – Unused Wellhead parts

Inspection Photos
Location Name: Bronco State AF10-64-1HN
Location ID: 431377




Photo 5 – Unmarked Risers




Photo 6 – Produced Water Tank missing NFPA Label