



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com)
Submission Date:	Apr 14, 2020 4:10:39 AM MDT
Server Receive Date:	Apr 14, 2020 4:10:50 AM MDT
Reference Number:	20200414-18139336494
Location:	1060 Co Rd 514, Ignacio, CO 81137, USA Apr 14, 2020 4:00:10 AM MDT [View Map]

Information

Name	kenneth.canterbury@crossfire-llc.com
Date	Apr 10, 2020
Well Name	TYCKSEN GAS UNIT A 1
API Number	50670716100
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean Up Land Owner Debris Repaired Berm Replaced/Repaired Tank Signs

Photo of first corrective action completed



Completed work description Corrective Action 1

Erosion repair

Photo of second corrective action completed



Completed work description of corrective action 2
Photo of third corrective action completed

Installed rock run downs



Completed work description of corrective action 3
Photo of fourth corrective action completed

Repaired berms



Completed work description
Completed work description of corrective action 4
Summary of all work completed

Replaced equipment sign

Picked up trash

Installed rock run down, repaired berms ,picked up trash, and replaced well equipment sign