



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Apr 21, 2020 1:10:20 PM MDT
Server Receive Date:	Apr 21, 2020 1:13:28 PM MDT
Reference Number:	20200421-18140299845
Location:	557 Airpark Dr, Durango, CO 81303, USA Apr 21, 2020 1:09:57 PM MDT [ <a href="#">View Map</a> ]

## Information

Name	colen@horizonenvservices.com
Date	Apr 20, 2020
Well Name	JONES, ARTHUR GAS UNIT A 1
Location Name (Other)	A3
API Number	50670701400
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Other

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

treated musk thistle along road

Photo of third corrective action completed



Completed work description of corrective action 3

treated musk thistle

Photo of fourth corrective action completed



Completed work description

treated Canada thistle

Completed work description of corrective action 4

treated noxious weeds

Additional photos



Additional photos



Completed work description  
Summary of all work completed

treated noxious weeds  
previous treatment dates 6/24/16, 8/1/17, 6/1/18,  
4/9/19