



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Cole Nichols (colen@horizonenvservices.com)
Submission Date: Apr 21, 2020 1:44:32 PM MDT
Server Receive Date: Apr 21, 2020 1:47:39 PM MDT
Reference Number: 20200421-18140307823
Location: 557 Airpark Dr, Durango, CO 81303, USA
Apr 21, 2020 1:47:13 PM MDT [[View Map](#)]

Information

Name colen@horizonenvservices.com
Date Apr 20, 2020
Well Name LUCERO GAS UNIT 1
API Number 50670698300
Select State Colorado
Work type COGCC Inspection AR
Action Complete Other
Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed




Completed work description of corrective action 2

treated musk thistle

Photo of third corrective action completed



Completed work description of corrective action 3
Photo of fourth corrective action completed



Completed work description
Completed work description of corrective action 4
Completed work description
Summary of all work completed

treated noxious weeds

treated Russian thistle
treated noxious weeds
treated noxious weeds
previous treatment dates 6/24/16, 7/21/17, 6/11/18,
4/22/19