

Inspection Photos
Location Name: Grizzly Hebron 12 0881
Location ID: 448834



Photo 1. Overview of location taken facing northeast.



Photo 2. E&P waste fluid in jet pump secondary containment.

Inspection Photos
Location Name: Grizzly Hebron 12 0881
Location ID: 448834



Photo 3. E&P waste fluid in jet pump secondary containment.



Photo 4. E&P waste fluid in jet pump secondary containment.