



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com)
Submission Date:	Apr 24, 2020 3:06:21 PM MDT
Server Receive Date:	Apr 24, 2020 3:06:54 PM MDT
Reference Number:	20200424-18140692458
Location:	1055 Mira Del Sol Dr, Durango, CO 81301, USA Apr 24, 2020 3:02:51 PM MDT [View Map]

Information

Name	kenneth.canterbury@crossfire-llc.com
Date	Apr 14, 2020
Well Name	GARCIA GAS UNIT 1
API Number	50670724600
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Fencing Erosion Repairs Install Rock Run Down Replaced/Repaired Tank Signs

Photo of first corrective action completed



Completed work description Corrective Action 1

Photo of second corrective action completed

Installed new tank sign



Completed work description of corrective action 2
Photo of third corrective action completed

Fixed drainage ditch



Completed work description of corrective action 3
Photo of fourth corrective action completed

Fixed fence



Completed work description
Completed work description of corrective action 4
Summary of all work completed

Installed rock run down
Cleaned up stains and trash
Fixed fence, installed new sign, repaired drainage ditch, cleaned up stains and picked up trash and installed rock run down