

Citation Oil & Gas Corp, Fallow 32-18 1
073-06262

Inspection #688307699

4/23/2020

Routine Inspection



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources



Colorado Oil and Gas Conservation Commission
39.13439, -103.46906, 79°
04/23/2020 02:27:11 PM



Stuffing box leak.


Colorado Oil and Gas Conservation Commission
39.18057, -103.48022, 5108.3ft, 34°
04/23/2020 02:28:37 PM



Colorado Oil and Gas Conservation Commission
39.18073, -103.48045, 5108.3ft, 115°
04/23/2020 02:28:14 PM



Colorado Oil and Gas Conservation Commission
39.18574, -103.49089, 5160.8ft, 72°
04/23/2020 02:31:50 PM



Colorado Oil and Gas Conservation Commission
39.18574, -103.49088, 5157.5ft, 61°
04/23/2020 02:31:53 PM



Berm is worn down from hoses.


Colorado Oil and Gas Conservation Commission
39.18581, -103.49088, 5160.8ft, 125°
04/23/2020 02:32:13 PM



Colorado Oil and Gas Conservation Commission
39.18562, -103.49086, 5157.5ft, 4°
04/23/2020 02:31:33 PM



Colorado Oil and Gas Conservation Commission
39.18581, -103.4909, 5167.3ft, 76°
04/23/2020 02:32:18 PM




Colorado Oil and Gas Conservation Commission
39.18584, -103.49089, 5167.3ft, 52°
04/23/2020 02:32:22 PM



Colorado Oil and Gas Conservation Commission
39.1858, -103.49077, 5157.5ft, 35°
04/23/2020 02:32:40 PM



Colorado Oil and Gas Conservation Commission
39.1858, -103.49078, 5160.8ft, 180°
04/23/2020 02:32:43 PM



Colorado Oil and Gas Conservation Commission
39.18579, -103.49074, 5164.0ft, 161°
04/23/2020 02:32:51 PM



Colorado Oil and Gas Conservation Commission
39.18551, -103.49085, 5144.4ft, 173°
04/23/2020 02:31:17 PM



SW corner of tank
battery location,
sediment is transported
off location.

Colorado Oil and Gas Conservation Commission
39.18538, -103.49112, 5101.7ft, 181°
04/23/2020 02:34:05 PM