

Pit Status Evaluation Form

Pit Overview:

Pit Name: UPRR 42 "AM" 1	Facility ID: 118533
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: AMOCO PRODUCTION COMPANY / 2500	
Updated Operator:	
Form 15 Pit Permit Doc #: 383070	Permit Date: 12/26/1978
Related Facilities: UPRR 42 PAN AM GU AM #1 (API 123-09215; Facility ID 241426; Loc ID 318503)	

County: WELD			
Township: 1N	Range: 67W	Section: 27	QQ: SWNE
Original Latitude/ Longitude: 40.023818 / -104.874342			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | |
|---|------------------|
| <input checked="" type="checkbox"/> Form 15 Pit Permit – Doc #: 383070 | Date: 12/26/1978 |
| <input checked="" type="checkbox"/> Field Inspection(s) – Doc #: 200072403 | Date: 5/2/2005 |
| Doc #: | Date: |
| Doc #: | Date: |
| <input type="checkbox"/> Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> Form 4 Sundry Notice – Doc #: | Date: |
| <input checked="" type="checkbox"/> COGIS Document – Doc #: 31856 | Date: 8/19/1996 |
| <input checked="" type="checkbox"/> Pit Inventory – Doc #: 2142986 | Date: 8/21/1997 |
| <input type="checkbox"/> Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

1997 pit inventory reports a fiberglass tank on location.

Pit Status Review Summary:

Based on records review and aerial imagery, any pits on location were replaced by a fiberglass tank prior to 8/21/1997 pit inventory report, which documents a 75bbl fiberglass tank on location. Battery was relocated ~2010. Pit Status has been changed to closed.

