

Final Reclamation Inspection

April 27, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP - #47120

Location ID: 327618

Inspection Document #: 697501410

Weld County, CO

SWNE Section 6 T3N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: LUDWIG #2-6
Location ID: 327618



Photo 1. Photo taken south of the plugged and abandoned location, facing North. Photo illustrates all equipment has been removed. This PA location is now going to be the Elkhead-Vega location which already commenced construction operations.