

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/20/2020

Submitted Date:

04/22/2020

Document Number:

699700126

FIELD INSPECTION FORMLoc ID 446962 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96700

Name of Operator: WILLIAMS COMPANIES INC* THE

Address: 1755 ARROYO DRIVE

City: BLOOMFIELD State: NM Zip: 87413

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Glen Jasek		glen.jasek@williams.com	Principal Agent
Fischer, Alex		alex.fischer@state.co.us	
Lutz, Deborah		debbie.lutz@state.co.us	
Ikenouye, Teri		teri.ikenouye@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446964	TANK BATTERY	AC	07/25/2016		-	Fawn Creek Drip Tank	EI

General Comment:

On April 20, 2020, COGCC Environmental Staff (John Heil) conducted an environmental field inspection of WILLIAMS COMPANIES INC* THE (Operator #96700) Fawn Creek Drip Tank Facility/Location ID 446962. The inspection was also conducted as Operator #96700 apparently was requesting a bond release, as the facility had been transferred to another operator.

LocationOverall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Sign not posted and information at the tank battery indicates Williams as the operator.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	05/22/2020

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLS	STEEL AST		,	
Comment:	COGCC records indicate that the Fawn Creek Drip Tank is under WILLIAMS COMPANIES INC* THE.					
Corrective Action:	Operator shall Submit an eForm 10. CERTIFICATE OF CLEARANCE AND/OR CHANGE OF OPERATOR and contact Teri Ikenouye.				Date:	05/07/2020

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:



Inspected FacilitiesFacility ID: 446964 Type: TANK API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402377827	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5129625
699700128	20200420 Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5129624